## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,987,383 B2 DATED : January 17, 20

DATED : January 17, 2006 INVENTOR(S) : Kusumoto et al.

7,383 B2 Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## Column 28,

Line 37, "first internal source line" should read -- first internal power source line --.
Line 64, "second internal source line" should read -- second internal power source line --.

## Column 29,

Line 8, "the first power source" should read -- a first power source --.

Line 16, "first internal source line" should read -- first internal power source line --.

## Column 30,

Line 14, "second internal source line" should read -- second internal power source line --.

Signed and Sealed this

Sixth Day of June, 2006

JON W. DUDAS
Director of the United States Patent and Trademark Office